

Base Map Reference:
Striplin Environmental Associates, Inc.
Hylebos Waterway Pre-Remedial Design Program, 1997.

Floyd & Snider Inc. EVANS-HAMILTON, INC. Pentec ENVIRONMENTAL

HYLEBOS WATE
WOOD DEBRIS F
Tacoma, Wash

6/20/98 FL-HYL-CSR5-8.0WG xref: base2.dwg



RWAY
ROGRAM
ington

Figure 5.8
Wood Debris Coverage
Based on Video Survey



Base Map Reference:
Striplin Environmental Associates, Inc.
Hylebos Waterway Pre-Remedial Design Program, 1997.

Floyd&Snider Inc. EVANS-HAMILTON, INC. Pentec ENVIRONMENTAL

HYLEBOS WATI
WOOD DEBRIS I
Tacoma, Was

6/20/98 FL-HYL-CSR5-9.DWG xref:base2.dwg

:RWAY
?ROGRAM
iington

Figure 5.9
Log Coverage Based on Video Survey & Side-Scan Sonar



Base Map Reference:
Striplin Environmental Associates, Inc.
Hylebos Waterway Pre-Remedial Design Program, 1997.

Floyd&Snider Inc. EVANS-HAMILTON, INC. Pentec ENVIRONMENTAL

HYLEBOS WAT
WOOD DEBRIS
Tacoma, Was

7/05/98 FL-HYL-CSR5-22.DWG xref:basel.dwg



RWAY
ROGRAM
ington

Figure 5.22
Wood Accumulation Areas